



PS500


 Quick Operation Guide



Switch On



Switch Off



OFF 3





OFF 2

OFF 1

Backlight On

Max

Min



Reset

Confidence Signal

Every 



Manual Datalog




Pump





Alarm Indicators





Gas Alarm Acknowledge




Self Test




Flow Fault




Zero Fault



Calibration Overdue



Battery Life



Charging

